




PLAN DE SITUATIE-**IN EXECUTIE**
SCARA 1:500

-EXTRAVILAN -
Teritoriul:
Adresa:
Beneficiar:
Supr. teren studiat: S= 11200 mp

DRAGANU ARGES
Com. Draganu, Sat Dumbravesti, D.N. 7,
km 136+400 stg. extravilan, jud. Arges
C.N.A.I.R. S.A.-D.R.D.P. BUCURESTI 13

ELIPSOID: Krasovski
PROIECTIA: Stereografica 1970
SISTEM ALTIMETRIC: Marea Neagra 1975



LEGENDA

↑	- Semnalizare drum
●	- Camin de vizitare
○	- Aerisiri drenuri
—	- Zid de sprijin
—	- Drum asfaltat
—	- Parapet de siguranta metalic
—	- Rigola
—	- Sant colector
—	- Frontul de desprindere al alunecarii de teren
—	- Suprafata de studiu
—	- Imobile cadastrate
—	- Limita zonei afectate de alunecare
—	- Suprapunere

REVIZIA:	Numele:	Data:	Motivul revizuirii si documentul pe baza caruia s-a facut revizia
ALMIRA SRL			
Bucuresti, str. Branduselor nr. 3A Corp 1			
RC: J /40/1748/1992			
DESENAT	FUNCTIA/NUME, PRENUME	SEMNATURA	SCARA
PROIECTAT	Teh. S. Cimpeanu		1:10000
DIRECTOR	Ing. G. Mihiu		Masa:
Ing. G. Mihiu			
Titlu plan:			
PLAN DE SITUATIE- IN EXECUTIE SCENARIU I			
Contract (nr./data): 154/14.06.2019			
Localitatea: BUCURESTI			
Beneficiar: D.R.D.P. BUCURESTI			
Faza: D.A.L.I.			
Cod documentatie: 154 - 2019 C			
A - 3721-2019			
Pi: 1			